

# TOOL MODEL TOM-35



## PRESSURE/TORQUE CONVERSION CHART

### Standard Torque Chart

PRESSURE IN PSI	TORQUE IN NM
--------------------	-----------------

1200	5753
1400	6712
1600	7671
1800	8630
2000	9589
2200	10548
2400	11507
2600	12466
2800	13425
3000	14384
3200	15343
3400	16302
3600	17260
3800	18219
4000	19178

PRESSURE IN PSI	TORQUE IN NM
--------------------	-----------------

4200	20137
4400	21096
4600	22055
4800	23014
5000	23973
5200	24932
5400	25891
5600	26850
5800	27808
6000	28767
6200	29726
6400	30685
6600	31644
6800	32603
7000	33562

PRESSURE IN PSI	TORQUE IN NM
--------------------	-----------------

7200	34521
7400	35480
7600	36439
7800	37398
8000	38357
8200	39315
8400	40274
8600	41233
8800	42192
9000	43151
9200	44110
9400	45069
9600	46028
9800	46987
10000	47946